



The reed relays need to be 5mA maximum. A COT0.9008 series, high sensitivity coil works.  
 The resistors are 1%. These can be 100 Ohm as well. Change the input summing resistor to IC1 to 7.8k as indicated.

SP_Kbd_Div_MTC64_relay_Low_1.1	
TITLE: Keybed divider and buss emulator Low	
Document Number:	REV:
Date: 5/20/2012 6:02:50 PM	Sheet: 1/1

